LP922-5XC Series -

2 = 0-2g

5 = 0-5g

10 = 0-10g


20 = 0-20g

P = Peak

PROTECTION & RELIABILITY OPTIMIZATION INSTRUMENTS

CONNECT TO CONFIDENCE

Class I, Division 2/Zone 2 Loop Power Sensor, For Use In "Non-Arcing, Non-Sparking" Environments, Top Exit Flying Leads, Acceleration, 4-20 mA Output



rdous Area Sensors & Accessories

Lifetime Warranty on Materials & Workmanship Page 335

24 inch flying leads with 1/4 inch NPT Mount

52C = 1 inch NPT with

24 inch flying leads and 1/2 inch NPT Mount

• 800-999-5290

Purchasing

Important

information on

Regulatory Approvals

and Requirements on Page 331